

SPIKE UDC 420D

- Fast exposure with excellent image quality
- Hard, durable stencils, resistant to the widest range of inks and additives
- Superior mesh adhesion
- Lightning fast washout and easy reclaim
- High viscosity allows coating on low or high mesh counts

SPIKE UDC-420D dual cure emulsion is designed for the widest range of imaging applications.

SPIKE UDC-420D direct emulsion allows screen makers to obtain remarkable image quality and exceptionally durable stencils. In addition, SPIKE UDC-420D's high viscosity allows for excellent coating on low or high mesh counts. For use with water, solvent, UV and plastisol based inks.

RECOMMENDED

Chromaline Exposure Calculator

Drying cabinet

Pressure washer

RECOMMENDED

Chroma/Haze™

Chroma/Brade™

haze remover

mesh abrader



MATERIALS REQUIRED

Exposure unit Washout sink Clean work area Scoop coater

CHEMICALS REQUIRED

Chroma/Clean[™] mesh degreaser

Chroma/Strip™ screen reclaimer

SAFETY AND HANDLING

Avoid contact with skin and eyes. Refer to MSDS for further information.

STANDARD SIZES

Quart, gallon, 3.5 gallon, 50 gal. drum

SPECIFICATIONS

Appearance: Solids: Viscosity: Other: Purple 36% (sensitized) 5360 CPS (sensitized) Available upon request

STORAGE

Shelf life for sensitized SPIKE UDC-420D emulsion is 4 to 6 weeks at room temperature (60 to 80°F). To maximize sensitized shelf life use only distilled water to dissolve diazo sensitizer.

Protect from freezing. SPIKE UDC 420D is not freeze/thaw stable.

Coated, unexposed screens can be stored as long as one month in a clean, cool, dry and completely dark area.

Expiration date. Always check the expiration date on sensitizer bottle to assure freshness.



www.chromaline.com

(800) 328-4261

WARNING: This product can expose you to chemicals including 1,4-dioxane, which is known in the State of California to cause cancer. For more information go to www.P65Warnings.ca.gov

f 🎽 🛗 🦻 in

An IKONICS Company | ISO 9001 Certified | NASDAQ Listed: IKNX







INSTRUCTIONS

DEGREASE

Using Chroma/Clean[™] mesh degreaser, work up a lather on both sides of mesh. Flood screen and frame thoroughly with garden type hose, then dry.

MIX

Mix emulsion and sensitizer according to instructions on bottle. Let emulsion stand at least two hours before using.

COAT

Fill scoop coater with room temperature emulsion. Slowly apply first coat to print side. Then coat squeegee side with one to three coats depending upon thickness required. If thicker stencil is required, additional coats may be applied to print side after initial drying of stencil. Be sure to dry thoroughly between coats.



DRY

Thoroughly dry screen in horizontal position, print side down, using a dark, clean drying cabinet. Temperature should not exceed 150°F (40°C).

EXPOSE

Place emulsion side of photopositive in contact with print side of screen.

DEVELOP

Gently spray both sides of screen with tepid water, wait 30

seconds then gently wash print side of the screen until image is fully open. Rinse both sides thoroughly. Dry screen completely and you are ready to print.



RECLAIM

Apply Chroma/Strip[™] screen reclaimer to both sides of screen. Scrub area to be reclaimed with a stiff nylon brush to ensure entire surface is wet and let it work a few moments until stencil begins to dissolve. Remove stencil residue with pressure washer, then rinse with garden type hose, thoroughly flooding screen and frame.



EXPOSURE GUIDELINES

Note: Exposure times are suggested only as a guide. Use the Chromaline Exposure Calculator to determine optimal exposure times. Individual exposure times may vary depending upon equipment used, bulb age, and other shop conditions.

SUGGESTED MINIMUM EXPOSURE GUIDELINES

Mesh	Time
158 mesh	60 sec.
230 mesh	45 sec.
305 mesh	30 sec.

Exposure times were set using a VNH unit. All screen mesh was orange in color. Screens were coated wet on wet once on print side and twice on squeegee side.

AVOID FAILURE: Dual cure emulsions have a very wide exposure latitude. Underexposed stencils often appear acceptable, but premature breakdown can occur on the press. When determining exposure speed, always overexpose your test stencil, then reduce exposure time until acceptable image quality is achieved. This will help assure good durability.

For Technical Service Call Toll Free **1-800-328-4261** Email: **help@chromaline.com**